



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**14036-36-4592**  
State Number  
**H1241**

EQUIPMENT INSPECTED

State Number: <b>H1241</b>	Type of Unit: Hand Lift	Floor to Floor: 1 to 3
Capacity: 750	Manuf: GARAVENTA	Speed: 10
Landings: 3	Installed: 04/24/2002	Rope Size:
Volts: 18	Complied:	Entrances: 2
OWNER	OCCUPANT	
GROVE PARK BAPTIST CHURCH	GROVE PARK BAPTIST CHURCH	
108 TRAIL ONE	108 TRAIL ONE	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 02/05/2014	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

1

VIOLATIONS

2.1.1.8	Place emergency lights in working order
6.6.1.1	Place cover over light at top of hoistway

Items must be corrected by: 03/07/2014

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: SUE ETHRIDGE 336-227-2910

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

GROVE PARK BAPTIST CHURCH  
108 TRAIL ONE  
BURLINGTON, NC, 27215