



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**14057-36-5825**  
State Number  
**16089**

EQUIPMENT INSPECTED

State Number: <b>16089</b>	Type of Unit: Passenger	Floor to Floor: B to 1F
Capacity: 2100	Manuf: THYSSEN KRUPP	Speed: 100
Landings: 3	Installed: 11/16/1995	Rope Size:
Volts: 208	Complied: 11/27/1995	Entrances: 2
OWNER	OCCUPANT	
ALAMANCE-BURLINGTON SCHOOL SYSTEM	EASTLAWN SCHOOL	
1712 VAUGHN RD	502 N GRAHAM HOPEDALE	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27217	

INSPECTION INFORMATION

Inspection Date 02/26/2014	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

1

VIOLATIONS

2.27.1.1.2 Put the in car emergency telephone in proper working order. (SECOND NOTICE) 10 DAYS

Items must be corrected by: 03/08/2014

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: johnny rodgers 336-516-0919

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ALAMANCE-BURLINGTON SCHOOL SYSTEM  
1712 VAUGHN RD  
BURLINGTON, NC, 27215