N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
14059-36-1185
State Number
9974

EQUIPMENT INSPECTED

State Number: **9974**
Capacity: 4000
Landings: 2
Volts: 480

Type of Unit: Passenger
Manuf: THYSSEN KRUPP
Installed: 11/10/1981
Complied: 11/10/1981

Floor to Floor: 1 to 2
Speed: 125
Rope Size:
Entrances: 1

OWNER
MEDTOX DIAGNOSTICS, INC
1238 ANTHONY RD
BURLINGTON, NC, 27215

OCCUPANT
MEDTOX DIAGNOSTICS, INC
1238 ANTHONY RD
BURLINGTON, NC, 27215

INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County
02/28/2014	Routine	Re-issued	36 - Kirkman	ALAMANCE

1

VIOLATIONS

none found

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: MARK 336-226-6311 Inspector _____

THIS IS NOT AN INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:
MEDTOX DIAGNOSTICS, INC
1238 ANTHONY RD
BURLINGTON, NC, 27215