



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
14063-52-0729
State Number
28358

EQUIPMENT INSPECTED

State Number: 28358	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2100	Manuf: CANTON	Speed: 100
Landings: 2	Installed: 07/25/2012	Rope Size:
Volts: 208	Complied:	Entrances: 1
OWNER	OCCUPANT	
AVERY COUNTY JAIL ANNEX	AVERY COUNTY JAIL ANNEX	
ATTN FINANCE DEPT	300 SCHULTZ CIRCLE	
NEWLAND, NC, 28657	NEWLAND, NC, 28657	

INSPECTION INFORMATION

Inspection Date 03/04/2014	Type Inspection Routine	Certificate Status Re-issued	Inspector 52 - Sosebee	County AVERY
-------------------------------	----------------------------	---------------------------------	---------------------------	-----------------

6

VIOLATIONS

2.9.1	Assign identification (numbers or letters) to the equipment where required.
8.6.4.7.4	Water and oil shall not be allowed to accumulate on pit floors. (May be from pit can overflowing.
8.6.5.5.2	Empty the pit can.
8.11.3.2.1	Perform the annual relief valve and system pressure test.
2.27.1.1.2	Put the in car emergency telephone in proper working order.
8.6	Perform the annual inspection on the machine room fire extinguisher.
8.6	Repair leak on machine room oil line.

Items must be corrected by: 04/03/2014

Elevator Name: # 2

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Avery County 828-733-8259

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

AVERY COUNTY JAIL ANNEX
ATTN FINANCE DEPT
NEWLAND, NC, 28657