

THIS IS NOT AN

INVOICE

An invoice will be mailed to:

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 14064-52-0752 State Number 9311

	EQ	UIPMENT INSPECTED		
State Number: 9311 Capacity: 2100 Landings: 2 Volts: 240 OWNER AVERY COUNTY SCI 775 CRANBERRY STE NEWLAND, NC, 2865	REET	RUPP	Floor to Floor: 1 to 2 Speed: 125 Rope Size: 0 Entrances: 1	
		PECTION INFORMATION		
Inspection Date 03/05/2014	Type Inspection Routine	Certificate Status Re-issued	Inspector 52 - Sosebee	County AVERY
		VIOLATIONS		
2 14 7 1 3	But the in car emergency light in working	order		
2.14.7.1.3 8.6	Put the in car emergency light in working Lock the emergency exit on top of the ele-			
	Lock the emergency exit on top of the ele			
8.6 Items must be correct	Lock the emergency exit on top of the election	vator.	een made in order to bring you	r equipment into

AVERY COUNTY SCHOOLS

775 CRANBERRY STREET NEWLAND, NC, 28657