



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
14065-52-5921
State Number
28117

EQUIPMENT INSPECTED

State Number: 28117	Type of Unit: Passenger	Floor to Floor: 1 to 3
Capacity: 2100	Manuf: TKE	Speed: 100
Landings: 3	Installed: 04/05/2012	Rope Size:
Volts: 208	Complied:	Entrances: 1
OWNER	OCCUPANT	
AVERY CO HUMANE SOCIETY INC	AVERY CO HUMANE SOCIETY SHELTER/OFFICE	
P O BOX 1213	279 NEW VALE ROAD	
NEWLAND, NC, 28657	NEWLAND, NC, 28657	

INSPECTION INFORMATION

Inspection Date 03/06/2014	Type Inspection Routine	Certificate Status Re-issued	Inspector 52 - Sosebee	County AVERY
-------------------------------	----------------------------	---------------------------------	---------------------------	-----------------

6

VIOLATIONS

2.2.5.1	Put the pit lights in proper working order. (May be the bulb.)
2.14.7.1.3	Put the in car emergency light in working order.
8.6.4.7.4	Remove the water from the pit floor. Oil alert monitor is not in alert and will not test.
2.2.2.4	Put the sump pump in proper working order and install cover.
8.6	Take steps to waterproof pit.

Items must be corrected by: 04/05/2014

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Avery County Animal Shelter 828-733-2333

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

AVERY CO HUMANE SOCIETY INC
P O BOX 1213
NEWLAND, NC, 28657