

THIS IS NOT AN

INVOICE

An invoice will be mailed to:

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 14070-36-461 State Number H823

1

| | 1 | EQUIPMENT INSPECTED | | | |
|---|-----------------------------------|---------------------------------|-------------------------------|-------------------------|--|
| State Number: H823 | Type of Unit: Han | d Lift | Floor to Floor: LL to U | L | |
| Capacity: 550 | Manuf: NATL W- | | Speed: 9 | | |
| Landings: 2 | Installed: 01/12/19 | 98 | Rope Size: | | |
| Volts: 110 | Complied: 02/02/1 | 998 | Entrances: 2 | | |
| OWNER | | O | CCUPANT | | |
| ALAMANCE - BURLINGTON SCHOOL SYSTEM | | Т | TURRENTINE MIDDLE SCHOOL | | |
| 1227 VAUGHN RD | | 1 | 1710 EDGEWOOD AVE | | |
| BURLINGTON, NC, 27217 | | | BURLINGTON, NC, 27215 | | |
| | IN | SPECTION INFORMATION | | | |
| Inspection Date 03/11/2014 | Type Inspection Routine | Certificate Status Re-issued | Inspector 36 - Kirkman | County ALAMANCE | |
| | | VIOLATIONS | | | |
| | | | | | |
| | | | | | |
| Notify the Elevator Bureau in write complainace with current codes. | ting on Corrected Violations Form | | have been made in order to br | ing your equipment into | |

Page 1 of 1

1227 VAUGHN RD BURLINGTON, NC, 27217

ALAMANCE - BURLINGTON SCHOOL SYSTEM