

THIS IS NOT AN INVOICE

An invoice will be mailed to:

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 14072-48-1530 State Number 23583

		EQUIPMENT INSPECTED		
State Number: 23583 Type of Unit		assenger	Floor to Flo	oor: 1 to 4
Capacity: 3000 Manuf: THYSSEN KRUPP		EN KRUPP	Speed: 125	
Landings: 4 Installed: 01/10/2006			Rope Size: .	
Volts: 208 Complied: 01/10/2006		0/2006	Entrances: 1	
OWNER OCCUPANT				
CAM ISLANDER RESORT - BLDG. #33				
P.O. BOX 8126		157 VIA OLD SOUND BLVD		
OCEAN ISLE BEACH, NC, 28469		OCEAN ISLE BEACH, NC, 28469		
	n	NSPECTION INFORMATION		
Inspection Date 03/13/2014	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK 1
		VIOLATIONS		
Items must be corrected by: 04. Notify the Elevator Bureau in writing complainace with current codes. Violations pointed out to: UNAVA	ng on Corrected Violations Form	n when the following corrections		bring your equipment into
Violations pointed out to: UNAVA		nailing address please call: 919-	Inspector	

P.O. BOX 8126

OCEAN ISLE BEACH, NC, 28469