NCDOL NCDOL N. Department of labor

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 14077-48-5885 State Number 21808

	EQUI	PMENT INSPECTED			
State Number: 21808	Type of Unit: Passenge	of Unit: Passenger		Floor to Floor: 1 to 4	
Capacity: 3000 Manuf: THYSSEN KRUPP			Speed: 125 Rope Size: 0		
Landings: 4	Installed: 07/31/2003				
Volts: 208 Complied: 07/3				1	
OWNER		OCCUPANT			
CAM		ISLANDER RESORT - BLDG. #28			
P.O. BOX 8126	3 JAN STREET				
OCEAN ISLE BEACH, NC, 28	469	OCEAN ISLE BEACH, NC, 28469			
	INSPEC	TION INFORMATION			
Inspection Date 03/18/2014	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK	
		VIOLATIONS			
Items must be corrected by: 0	4/17/2014				
	ting on Corrected Violations Form when	the following corrections	have been made in order to	bring your equipment into	
Violations pointed out to: UNAV	AILABLE		Inspector		
	To make changes to the invoice mailing address please call: 919-733-0372				
THIS IS NOT AN INVOICE	An invoice will be mailed to:	CAM P.O. BOX 8126 OCEAN ISLE REACH			