



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
14078-48-0099
State Number
24237

EQUIPMENT INSPECTED

State Number: 24237	Type of Unit: Passenger	Floor to Floor: 1 to 3
Capacity: 2500	Manuf: OTIS	Speed: 125
Landings: 3	Installed: 01/30/2007	Rope Size: 0
Volts: 208	Complied: 01/30/2007	Entrances: 1
OWNER	OCCUPANT	
CHAD MORRIS	YAUPON DUNES	
371 NORTH BILHEN STREET	700 OCEAN DRIVE	
TROY, NC, 27371	OAK ISLAND, NC, 28461	

INSPECTION INFORMATION

Inspection Date 03/19/2014	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK
-------------------------------	----------------------------	---------------------------------	--------------------------	---------------------

10

VIOLATIONS

8.6.4.7.1 Clean the elevator pit.

Items must be corrected by: 04/18/2014

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: UNAVAILABLE

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

CHAD MORRIS
371 NORTH BILHEN STREET
TROY, NC, 27371