



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
14093-36-089
State Number
H1200

EQUIPMENT INSPECTED

State Number: H1200	Type of Unit: Hand Lift	Floor to Floor: 1 to 2
Capacity: 750	Manuf: VPL GERA VEN	Speed: 11
Landings: 2	Installed: 10/26/2001	Rope Size:
Volts: 220	Complied: 10/26/2001	Entrances: 2

OWNER

ALAMANCE CO SCHOOLS
1712 VAUGHAN RD
BURLINGTON, NC, 27217

OCCUPANT

HOLT ELEM SCHOOL
4751 S HWY 62
BURLINGTON, NC, 27215

INSPECTION INFORMATION

Inspection Date 04/03/2014	Type Inspection Not Inspected	Certificate Status Not Issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------------	----------------------------------	---------------------------	--------------------

1

VIOLATIONS

PLACE HADI-CAP LIFT IN PROPER WORKING ORDER.

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: reginald davis 336-570-6195

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ALAMANCE CO SCHOOLS
1712 VAUGHAN RD
BURLINGTON, NC, 27217