



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**14094-48-0253**  
State Number  
**13918**

EQUIPMENT INSPECTED

State Number: <b>13918</b>	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2500	Manuf: EASTERN	Speed: 100
Landings: 2	Installed: 04/19/1990	Rope Size:
Volts: 240	Complied: 04/27/1990	Entrances: 1
OWNER	OCCUPANT	
BRANTLEY PROPERTIES INC	WOODCROFT APARTMENT	
209 MERCER HILL RD	209 MERCER MILL RD	
ELIZABETHTOWN, NC, 28327	ELIZABETHTOWN, NC, 27893	

INSPECTION INFORMATION

Inspection Date 04/04/2014	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BLADEN
-------------------------------	----------------------------	---------------------------------	--------------------------	------------------

9

VIOLATIONS

8.6.8.9 Signs. Caution signs shall be provided. Damaged or missing signs shall be replaced. ALL FLS.  
3.24.1 Elevator pumping unit. [REPLACE DAMAGED OIL LINE HOSE [BUBBLE].

Items must be corrected by: 05/04/2014

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: JUNIE

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

BRANTLEY PROPERTIES INC  
209 MERCER HILL RD  
ELIZABETHTOWN, NC, 28327