

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 14104-48-577 State Number 24471

| | EQU | IPMENT INSPECTED | | |
|---|--|---------------------------------|---|---------------------|
| State Number: 24471 Capacity: 2100 Landings: 2 Volts: 208 OWNER NEWBRIDGE BANK 5201 SOUTHPORT SUPPLY RD | Type of Unit: Passenger Manuf: SCHINDLER, HYD Installed: 12/14/2006 Complied: OCCUPANT NEWBRIDGE 5201 SOUTH | | Floor to Floor: 1 to 2 Speed: 100 Rope Size: 0 Entrances: 1 BANK ORT SUPPLY RD | |
| SOUTHPORT, NC, 28465 | SOUTHPORT, NC, 28465 | | | |
| | INSPE | CTION INFORMATION | | |
| Inspection Date 04/14/2014 | Type Inspection Routine | Certificate Status Re-issued | Inspector 48 - Martin | County BRUNSWICK |
| | | VIOLATIONS | | |
| 8.6.4.7.4 8.11.3.2.1 | Remove the oil from the pit floor. Perform the annual relief valve test | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

Items must be corrected by: 05/14/2014 Elevator Name: # 1

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: MEGAN PIERCE Inspector

THIS IS NOT AN INVOICE

To make changes to the invoice mailing address please call: $919\mbox{-}733\mbox{-}0372$

An invoice will be mailed to:

NEWBRIDGE BANK
5201 SOUTHPORT SUPPLY RD
SOUTHPORT, NC, 28465

Page 1 of 1