



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
14126-48-3521
State Number
24949

EQUIPMENT INSPECTED

State Number: 24949	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2500	Manuf: OTIS	Speed: 100
Landings: 2	Installed: 06/26/2007	Rope Size:
Volts: 480	Complied:	Entrances: 1
OWNER	OCCUPANT	
TRINITY UNITED METHODIST CHURCH	TRINITY UNITED METHODIST CHURCH	
209 E. NASH ST	209 E. NASH ST	
SOUTHPORT, NC, 28461	SOUTHPORT, NC, 28461	

INSPECTION INFORMATION

Inspection Date 05/06/2014	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK
-------------------------------	----------------------------	---------------------------------	--------------------------	---------------------

10

VIOLATIONS

8.6.5.5.2	Empty the drain bucket in the pit.
2.27.1.1.2	Put the in car emergency telephone in proper working order.

Items must be corrected by: 06/05/2014

Elevator Name: # 1

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: PAM

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

TRINITY UNITED METHODIST CHURCH
209 E. NASH ST
SOUTHPORT, NC, 28461