



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
14143-17-2630
State Number
14541

EQUIPMENT INSPECTED

| | | |
|----------------------------|---------------------------|------------------------|
| State Number: 14541 | Type of Unit: Passenger | Floor to Floor: 1 to 2 |
| Capacity: 4000 | Manuf: SCHINDLER | Speed: 100 |
| Landings: 2 | Installed: 02/27/1992 | Rope Size: |
| Volts: 440 | Complied: 03/18/1992 | Entrances: 1 |
| OWNER | OCCUPANT | |
| ASHEVILL REGIONAL AIRPORT | ASHEVILL REGIONAL AIRPORT | |
| 61 TERMINAL DRIVE | 61 TERMINAL DRIVE | |
| FLETCHER, NC, 28732 | FLETCHER, NC, 28732 | |

INSPECTION INFORMATION

| | | | | | |
|-------------------------------|----------------------------|---------------------------------|-------------------------|--------------------|------|
| Inspection Date 05/23/2014 | Type Inspection Routine | Certificate Status Re-issued | Inspector 17 - White | County BUNCOMBE | 11 A |
|-------------------------------|----------------------------|---------------------------------|-------------------------|--------------------|------|

VIOLATIONS

2.14.7.1.3 Put the in car emergency light and alarm button in working order.

Items must be corrected by: 06/22/2014

Elevator Name: new

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Duane 828-654-3232

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ASHEVILL REGIONAL AIRPORT
61 TERMINAL DRIVE
FLETCHER, NC, 28732