

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 14162-52-0821 State Number 23277

	919-	101-1921		
	EQUIP	MENT INSPECTED		
State Number: 23277	Type of Unit: Passenger	of Unit: Passenger		
Capacity: 2100 Manuf: THYSSEN KRUPP Landings: 2 Installed: 07/28/2005		JPP	Speed: 80 Rope Size: 0	
Volts: 208	Complied: 02/16/2006		Entrances: 1	
OWNER		OCCUPANT		
		ELK RIVER CLU	ER CLUBHOUSE B HOUSE DRIVE	
		235 CLUB HOUS		
BANNER ELK, NC, 28604 BANNER E			LK, NC, 28604	
	INSPECT	TION INFORMATION		
Inspection Date 06/11/2014	Type Inspection Routine	Certificate Status Re-issued	Inspector 52 - Sosebee	County AVERY 6
·		VIOLATIONS		
machine rooms.  8.6 Remove water from m	achine room floor.			
complainace with current codes.	ing on Corrected Violations Form when the	ne following corrections have be		
Violations pointed out to: Elk Riv	ver Clubhouse 828-896-9773		Inspector	
	To make changes to the invoice mailing address please call: 919-733-0372			
THIS IS NOT AN INVOICE	An invoice will be mailed to:	ELK RIVER COUNTRY CLU 1000 CLUBHOUSE DRIVE BANNER ELK, NC, 28604	В	