

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 14167-48-2126 State Number H2175

	EQU	IPMENT INSPECTED		
State Number: H2175	Type of Unit: Har	nd Lift	Floor to Floor: 1 to 2	
Capacity: 750	Manuf: TKE		Speed: 20	
Landings: 2	Installed: 11/12/20	009	Rope Size:	
Volts: 120	Complied: 11/12/2	2009	Entrances: 2	
OWNER		OCCUPANT		
FIRST BAPTIST CHURCH	FIRST BAPTIST CHURCH			
521 MARTIN LUTHER KING JR	ST	521 MARTIN LUTHER KING JR ST		
BLADENBORO, NC, 28320		BLADENBORO, NC, 28320		
	INSPE	CTION INFORMATION		
Inspection Date 06/16/2014	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BLADEN
		VIOLATIONS		
complainace with current codes.		Elevator Name: SANCTUARY In the following corrections have been made in order to bring your equipment into		
Violations pointed out to: UNAVAIL			Inspector	
	To make changes to the invoice mailing address please call: 919-733-0372			
THIS IS NOT AN INVOICE An	invoice will be mailed to:	FIRST BAPTIST CHURCH 521 MARTIN LUTHER KING BLADENBORO, NC, 28320	G JR ST	