



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
14169-36-2831
State Number
22475

EQUIPMENT INSPECTED

State Number: 22475	Type of Unit: Passenger	Floor to Floor: 1 to 3
Capacity: 2500	Manuf: SCHINDLER	Speed: 125
Landings: 3	Installed: 05/25/2004	Rope Size: 0
Volts: 460	Complied: 05/25/2004	Entrances: 1
OWNER	OCCUPANT	
AKG	AKG	
7315 OAK WOOD ST EXT	7315 OAK WOOD ST EXT	
MEBANE, NC, 27302	MEBANE, NC, 27302	

INSPECTION INFORMATION

Inspection Date 06/18/2014	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

1

VIOLATIONS

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: TAMMY ANDREWS 919-563-4286

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

AKG
7315 OAK WOOD ST EXT
MEBANE, NC, 27302