

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 14218-7-5273 State Number 29345

	EQU	JIPMENT INSPECTED		
State Number: 29345	Type of Unit: Pass	enger	Floor to Floor: 1 to 2	
Capacity: 2500	Manuf: CANTON		Speed: 100	
Landings: 2 Installed:			Rope Size:	
Volts: 208	Complied:		Entrances: 1	
OWNER	•	OCCUPANT		
ST FRANCIS CATHOLIC CHURCH		ST FRANCIS CATHOLIC CHURCH		
167 ST FRANCIS PLACE		167 ST FRANCIS PLACE		
JEFFERSON, NC, 28640		JEFFERSON, NC, 28640		
	INSPE	ECTION INFORMATION		
Inspection Date 08/06/2014	Type Inspection New	Certificate Status Not Issued	Inspector 7 - Hoffman	County ASHE
		VIOLATIONS		
complainace with current codes Violations pointed out to: VER	riting on Corrected Violations Form whe		Inspector	
	T 1 1 4 4 1 1 1 1			
THIS IS NOT AN INVOICE	To make changes to the invoice mailing address please call: 919-733-0372			
	An invoice will be mailed to:	ST FRANCIS CATHOLIC CH 167 ST FRANCIS PLACE JEFFERSON, NC, 28640	IURCH	