



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**14224-8-3012**  
State Number  
**10528**

EQUIPMENT INSPECTED

State Number: <b>10528</b>	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2500	Manuf: THYSSEN KRUPP	Speed: 100
Landings: 2	Installed: 05/24/1983	Rope Size:
Volts: 208	Complied: 05/24/1983	Entrances: 1
OWNER	OCCUPANT	
ANSON CO ADMIN BLDG	ANSON CO COURTHOUSE	
101 S.GREENE ST	114 N GREENE ST	
WADESBORO, NC, 28170	WADESBORO, NC, 28170	

INSPECTION INFORMATION

Inspection Date 08/12/2014	Type Inspection Routine	Certificate Status Re-issued	Inspector 8 - Burris	County ANSON
-------------------------------	----------------------------	---------------------------------	-------------------------	-----------------

4

VIOLATIONS

8.6.4.7	CLEAN OIL OFF PIT FLOOR
8.6.4.15	RESTORE OPERATION OF ELEVATOR EMERGENCY LIGHTS.

Items must be corrected by: 09/11/2014

Elevator Name: VISITOR ELEVATOR

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: WENDELL WILLIAMSON 704.694.2796

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ANSON CO ADMIN BLDG  
101 S.GREENE ST  
WADESBORO, NC, 28170