



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**14226-8-1945**  
State Number  
**7235**

EQUIPMENT INSPECTED

State Number: <b>7235</b>	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 1500	Manuf: THYSSEN KRUPP	Speed: 75
Landings: 2	Installed: 09/19/1972	Rope Size:
Volts: 220	Complied: 06/20/2000	Entrances: 1
OWNER	OCCUPANT	
ANSON CO ADMIN BLDG	HAMPTON B ALLEN LIBRARY	
101 S. GREENE ST	120 S GREENE ST	
WADESBORO, NC, 28170	WADESBORO, NC, 28170	

INSPECTION INFORMATION

Inspection Date 08/14/2014	Type Inspection Routine	Certificate Status Re-issued	Inspector 8 - Burris	County ANSON
-------------------------------	----------------------------	---------------------------------	-------------------------	-----------------

4

VIOLATIONS

8.6.4	SECURE OIL PIT CAN TO DRAIN HOSE
2.2.2.4	CLEAN & PAINT RUSTED PIT CHANNEL
2.2.2.3	KEEP WATER OUT OF PIT

Items must be corrected by: 09/13/2014

Elevator Name: PASSENGER ELEVATOR

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: DONALD PERKINS 704.694.2796

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ANSON CO ADMIN BLDG  
101 S. GREENE ST  
WADESBORO, NC, 28170