

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 14226-8-4764 State Number H2233

	EQU	JIPMENT INSPECTED			
State Number: H2233	Type of Unit: Hai	nd Lift	Floor to Floor: 1 to 2		
Capacity: 750	Manuf: SAVARI		Speed: 14		
Landings: 2 Installed: 08/23/2010		010	Rope Size:		
Volts: 110	Complied:		Entrances: 1		
OWNER	1	OCCUPANT			
ANSON ANSON CO BOAR	D OF EDUCATION		EMENTARY SCHOOL		
320 CAMDEN ROAD			321 CAMDEN ROAD		
WADESBORO, NC, 28170		WADESBORO, NC, 28170			
WADESBORO, NC, 28170					
	INSPE	CTION INFORMATION			
Inspection Date 08/14/2014	Type Inspection Routine	Certificate Status Re-issued	Inspector 8 - Burris	County ANSON	
		VIOLATIONS			
complainace with current codes Violations pointed out to: GAI	vriting on Corrected Violations Form whes. RY COOPER 704.694.2725	-	Inspector		
	To make changes to the invoice mailin				
THIS IS NOT AN INVOICE	To make changes to the invoice mailing address please call: 919-733-0372 ANSON ANSON CO BOARD OF EDUCATION				
	An invoice will be mailed to:	320 CAMDEN ROAD WADESBORO, NC, 28170	OF EDUCATION		