



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
14239-48-4610
State Number
23850

EQUIPMENT INSPECTED

State Number: 23850	Type of Unit: Passenger	Floor to Floor: 1 to 3
Capacity: 3000	Manuf: OTIS	Speed: 150
Landings: 3	Installed: 06/02/2006	Rope Size: 0
Volts: 208	Complied:	Entrances: 1
OWNER		OCCUPANT
COMMUNITY ASSOCIATION MANAGEMENT		COLONY II BLDG 6
PO BOX 8126		908 RESORT CIRLCE
OCEAN ISLE BEACH, NC, 28469		SUNSET BEACH, NC, 28467

INSPECTION INFORMATION

Inspection Date 08/27/2014	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK
-------------------------------	----------------------------	---------------------------------	--------------------------	---------------------

10

VIOLATIONS

8.6.4.7.4	Remove the water from the pit floor. [SAME AS LAST YR].
2.27.1.1.2	Put the in car emergency telephone in proper working order. [SAME AS LAST YR.]

Items must be corrected by: 09/26/2014

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: UNAVAILABLE

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

COMMUNITY ASSOCIATION MANAGEMENT
PO BOX 8126
OCEAN ISLE BEACH, NC, 28469