

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-807-2770

Report Number
14262-48-0395
State Number
11519

EQUIPMENT INSPECTED

State Number: 11519	Type of Unit: Passenger	Floor to Floor: 1 to 6
Capacity: 4000	Manuf: SOUTHERN	Speed: 100
Landings: 6	Installed: 09/04/1986	Rope Size: 5/8
Volts: 480	Complied: 10/16/1986	Entrances: 1
OWNER	OCCUPANT	
ELIZABETHTOWN LUMBERTON POWER	ELIZABETHTOWN LUMBERTON POWER	
PO BOX 1899	3100 W BROAD ST	
ELIZABETHTOWN, NC, 28337	ELIZABETHTOWN, NC, 28337	

INSPECTION INFORMATION

Inspection Date 09/19/2014	Type Inspection Removed	Certificate Status Not Issued	Inspector 48 - Martin	County BLADEN
-------------------------------	----------------------------	----------------------------------	--------------------------	------------------

9

VIOLATIONS

n/a Car still under repair

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Unavailable

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ELIZABETHTOWN LUMBERTON POWER
PO BOX 1899
ELIZABETHTOWN, NC, 28337