



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
14268-59-5597
State Number
11322

EQUIPMENT INSPECTED

State Number: 11322	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2000	Manuf: CEMCO	Speed: 115
Landings: 2	Installed: 08/02/1985	Rope Size:
Volts: 220	Complied: 08/06/1985	Entrances: 1

OWNER

AMERICAN RED CROSS
100 EDGEWOOD RD
ASHEVILLE, NC, 28804

OCCUPANT

AMERICAN RED CROSS
100 EDGEWOOD RD
ASHEVILLE, NC, 28804

INSPECTION INFORMATION

Inspection Date 09/25/2014	Type Inspection Routine	Certificate Status Re-issued	Inspector 59 - Cannon	County BUNCOMBE	11 B
-------------------------------	----------------------------	---------------------------------	--------------------------	--------------------	------

VIOLATIONS

note no violations

Items must be corrected by: 09/25/2014

Elevator Name: ELEVATOR # 1

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Chris Smalls/828-258-3888

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

AMERICAN RED CROSS
100 EDGEWOOD RD
ASHEVILLE, NC, 28804