



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
14283-36-4171
State Number
8437

EQUIPMENT INSPECTED

State Number: 8437	Type of Unit: Freight	Floor to Floor: 1 to 3
Capacity: 10000	Manuf: SOUTHERN	Speed: 60
Landings: 3	Installed: 07/25/1988	Rope Size:
Volts: 480	Complied: 04/25/1989	Entrances: 1
OWNER	OCCUPANT	
NOVA FLEX HOSE CO	NOVA FLEX HOSE CO	
SR 1928/TROLLINGWOOD ROAD	SR 1928/TROLLINGWOOD ROAD	
HAW RIVER, NC, 27258	HAW RIVER, NC, 27258	

INSPECTION INFORMATION

Inspection Date 10/10/2014	Type Inspection Not Inspected	Certificate Status Not Issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------------	----------------------------------	---------------------------	--------------------

1

VIOLATIONS

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: KENNETH JONES 336-578-2161

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

NOVA FLEX HOSE CO
SR 1928/TROLLINGWOOD ROAD
HAW RIVER, NC, 27258