

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 14294-52-563 State Number 11158

6

EQUIPMENT INSPECTED

State Number: 11158 Type of Unit: Passenger Floor to Floor: L to 10

 Capacity: 2500
 Manuf: THYSSEN KRUPP
 Speed: 350

 Landings: 11
 Installed: 09/10/1985
 Rope Size: 5/8

 Volts: 208
 Complied: 03/24/2006
 Entrances: 1

OWNER OCCUPANT

SUGAR TOP HOMEOWNERS

303 SUGAR TOP DRIVE

BANNER ELK, NC, 28604

SUGAR TOP RESORT

303 SUGAR TOP DRIVE

BANNER ELK, NC, 28604

INSPECTION INFORMATION

Inspection DateType InspectionCertificate StatusInspectorCounty10/21/2014RoutineRe-issued52 - SosebeeAVERY

VIOLATIONS

2.11.11.8 Provide missing upthrust roller on the cab door.

2.11.11.6 Provide the missing door guides where needed. 1st floor

Note Monitor hoist rope rouge.

Items must be corrected by: 11/20/2014 Elevator Name: # 3

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: Sam 828-898-5226 Inspector

To make changes to the invoice mailing address please call: 919-733-0372

THIS IS NOT AN INVOICE

An invoice will be mailed to: 303 SUGAR 1

SUGAR TOP HOMEOWNERS 303 SUGAR TOP DRIVE BANNER ELK, NC, 28604