

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 14304-7-357 State Number 27737

	EQI	UIPMENT INSPECTED			
State Number: 27737	Type of Unit: Pass	senger	Floor to Floor: 1 to 3		
Capacity: 2500 Manuf: TKE		Speed: 100			
Landings: 3	Installed: 09/07/2011		Rope Size:		
Volts: 208	Complied: 09/07/2	2011	Entrances: 2		
OWNER		OCCUPANT			
MIDWAY BAPTIST CHURCI	Н	MIDWAY BAPTIST CHURCH			
1670 MT JEFFERSON ROAD		1670 MT JEFFERSON ROAD			
WEST JEFFERSON, NC, 2869		WEST JEFFERSON, NC, 28640			
	INSPI	ECTION INFORMATION			
Inspection Date 10/31/2014	Type Inspection Routine	Certificate Status Re-issued	Inspector 7 - Hoffman	County ASHE	
		VIOLATIONS			
NONE					
Notify the Elevator Bureau in wr complainace with current codes.	iting on Corrected Violations Form who	en the following corrections have b	een made in order to bring your e	quipment into	
Violations pointed out to: MIDWAY BAPTIST CH. 336-246-2012			Inspector		
	To make changes to the invoice mailing				
THIS IS NOT AN INVOICE	An invoice will be mailed to:	MIDWAY BAPTIST CHURCI 1670 MT JEFFERSON ROAD WEST JEFFERSON, NC, 2869			