

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 14307-7-5527 State Number 23882

5

	E	QUIPMENT INSPECTED			
State Number: 23882	Type of Unit: Pa		Floor to Floor: 1 to 2		
Capacity: 2500 Manuf: CEMCO			Speed: 90		
Landings: 2 Volts: 240			Rope Size: 0 Entrances: 1		
	Complied.		Entrances. 1		
OWNER W JEFFERSON UNITED METHODIST CHURCH		OCCUPANT W INTERPRODUCTION OF THE PRODUCT OF			
107 W 2ND STREET			W JEFFERSON UNITED METHODIST CH 107 W 2ND STREET		
WEST JEFFERSON, NC, 28694		WEST JEFFERSON, NC, 28694			
WEST JEFFERSON, NC, 280		WEST JETTERSON	, INC, 28094		
	INS	PECTION INFORMATION			
Inspection Date 11/03/2014	Type Inspection Routine	Certificate Status Re-issued	Inspector 7 - Hoffman	County ASHE	
		VIOLATIONS			
NONE					
NONE					
Notify the Elevator Bureau in wi	riting on Corrected Violations Form w	then the following corrections have bee	n made in order to bring your e	quipment into	
Violations pointed out to: KAREN HARTZOG 336-246-5292			Inspector		
		ling address please call: 919-733-0372			
THIS IS NOT AN INVOICE	An invoice will be mailed to:	invoice will be mailed to: W JEFFERSON UNITED METHODIST CHURCH 107 W 2ND STREET WEST JEFFERSON, NC, 28694			