NCDOL NCDOL NA Department of John

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 14308-48-3747 State Number 23791

		EQUIPMENT INSPECTED			
State Number: 23791 Capacity: 2500 Landings: 5	Type of Unit: Special Manuf: SCHINDLER Installed: 04/26/2006		Floor to Floor: 1 to 5 Speed: 125 Rope Size: 0		
Volts: 208	Complied:	Complied:		Entrances: 1	
OWNER	•	OCCUPANT			
CAMS		THE PRESERVE BUILDING #2 - CAR#2 2100 MARSH GROVE LANE OAK ISLAND, NC, 28465			
1630 MILITARY CUTOFF RE).				
WILMINGTON, NC, 28403					
	Γ	NSPECTION INFORMATION			
Inspection Date 11/04/2014	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK 1	
		VIOLATIONS			
2.2.2.4 Install the cover on the 8.6.4.7.4 Remove the oil from the N/A HANDRAIL LOOSE					
Items must be corrected by: I Notify the Elevator Bureau in wri complainace with current codes. Violations pointed out to: Unava	iting on Corrected Violations Forn		Inspector	bring your equipment into	
		ilima addmass mlassa salli 010.7			
THIS IS NOT AN INVOICE	An invoice will be mailed to:	mailing address please call: 919-7 CAMS 1630 MILITARY CUTC WILMINGTON, NC, 28	OFF RD.		