## NCDOL NCDOL NA Department of later

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 14308-48-4543 State Number 24167

		EQUIPMENT INSPECTED		
State Number: 24167 Capacity: 2500 Landings: 5 Volts: 208	Manuf: SCHI Installed: 02/2	Type of Unit: Passenger Floor to Floor: 1 to 5  Manuf: SCHINDLER Speed: 125  Installed: 02/28/2007 Rope Size: 0  Complied: 03/01/2007 Entrances: 1  OCCUPANT  THE PRESERVE, BLDG #3, CAR #3  3100 MARSH GROVE LANE  OAK ISLAND, NC, 28465		1 to 5
OWNER CAMS 1630 MILITARY CUTOFF R WILMINGTON, NC, 28403				
	n	NSPECTION INFORMATION		
Inspection Date 11/04/2014	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK 1
		VIOLATIONS		
2.2.2.4 Install the cover of Remove the oil fr Signs. Caution sig		nissing signs shall be replaced. [3	SRD. & 4TH. FLS.]	
complainace with current codes	riting on Corrected Violations Forn	n when the following corrections		
Violations pointed out to: Unav				
THIS IS NOT AN INVOICE	To make changes to the invoice r An invoice will be mailed to:	nailing address please call: 919-/ CAMS 1630 MILITARY CUTO WILMINGTON, NC. 28	OFF RD.	