



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

### INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**14308-48-5158**  
State Number  
**24166**

### EQUIPMENT INSPECTED

State Number: <b>24166</b>	Type of Unit: Passenger	Floor to Floor: 1 to 5
Capacity: 2500	Manuf: SCHINDLER, HYD	Speed: 125
Landings: 5	Installed: 02/28/2007	Rope Size: 0
Volts: 208	Complied: 03/01/2007	Entrances: 1
OWNER	OCCUPANT	
CAMS	THE PRESERVE BLDG #3 - CAR #2	
1630 MILITARY CUTOFF RD.	3100 MARSH GROVE LANE	
WILMINGTON, NC, 28403	OAK ISLAND, NC, 28465	

### INSPECTION INFORMATION

Inspection Date 11/04/2014	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK
-------------------------------	----------------------------	---------------------------------	--------------------------	---------------------

10

### VIOLATIONS

2.2.2.4	Put the sump pump in proper working order.
2.2.2.4	Install the cover on the sump pump.
8.6.4.7.4	Remove the oil from the pit floor.
2.26.12	Provide Braille where needed. [2ND. FL.]
8.6.8.9	Signs. Caution signs shall be provided. Damaged or missing signs shall be replaced. [4TH. FL.]

Items must be corrected by: 12/04/2014

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Unavailable

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

CAMS  
1630 MILITARY CUTOFF RD.  
WILMINGTON, NC, 28403