



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
14310-48-5910
State Number
H1132

EQUIPMENT INSPECTED

State Number: H1132	Type of Unit: Hand Lift	Floor to Floor: 1 to 2
Capacity: 750	Manuf: SAVARIA	Speed: 14
Landings: 2	Installed: 05/17/2001	Rope Size:
Volts: 120	Complied: 05/17/2001	Entrances: 2

OWNER

DANNY LEONORD - DOT KENNEDY
PO BOX 775
OAK ISLAND, NC, 28465

OCCUPANT

INTRACOASTAL REALTY CORP.
128 COUNTRY CLUB DR
OAK ISLAND, NC, 28465

INSPECTION INFORMATION

Inspection Date 11/06/2014	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK
-------------------------------	----------------------------	---------------------------------	--------------------------	---------------------

10

VIOLATIONS

8.6.4.7.1 Clean the elevator pit.

Items must be corrected by: 12/06/2014

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: MGMT.

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

DANNY LEONORD - DOT KENNEDY
PO BOX 775
OAK ISLAND, NC, 28465