N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
14318-7-5232
State Number
H1026

EQUIPMENT INSPECTED

State Number: **H1026**
Capacity: 495
Landings: 2
Volts: 220

Type of Unit: Hand Lift
Manuf: GARAVENTA
Installed: 02/01/2000
Complied: 02/21/2000

Floor to Floor: 1 to 2
Speed: 20
Rope Size:
Entrances: 2

OWNER
ASHE CO SCHOOLS
PO BOX 604
JEFFERSON, NC, 28640

OCCUPANT
ASHE CO MIDDLE SCHOOL
255 NORTHWEST LANE
WARRENSVILLE, NC, 28693

INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County
11/14/2014	Routine	Re-issued	7 - Hoffman	ASHE

5

VIOLATIONS

NONE

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: KENNY RICHARDSON 336-246-7175 Inspector _____

THIS IS NOT AN INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:
ASHE CO SCHOOLS
PO BOX 604
JEFFERSON, NC, 28640