

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 14357-48-1882 State Number 27879

EQUIPMENT INSPECTED					
State Number: 27879 Capacity: 2500 Landings: 2 Volts: 208 Type of Unit: P Manuf: TKE Installed: 06/10 Complied: 06/1		10/2011	Speed: 125 Rope Size:	Rope Size: Entrances: 1 LLOTTE	
OWNER FIRST BANK 10 WATERFORD BUS CTR W BELVILLE, NC, 28451	-	Complied: 06/10/2011 OCCUPANT FIRST BANK BUILDING - SHALLO NC HWY 130 WHITEVILLE ROAD SHALLOTTE, NC, 28459			
	Γ	NSPECTION INFORMATION			-
Inspection Date 12/23/2014	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK	10
		VIOLATIONS			
8.11.2.2.2	Perform the annual no load safe	ty test			
Items must be corrected by: 0	1/22/2015		Elevator Nan	ne: # 1	
Notify the Elevator Bureau in writ	ing on Corrected Violations Form	n when the following corrections	have been made in order to	bring your equipment into	

To make changes to the invoice mailing address please call: 919-733-0372

THIS IS NOT AN INVOICE

complainace with current codes.

Violations pointed out to: DARLA

An invoice will be mailed to:

FIRST BANK 10 WATERFORD BUS CTR WAY

Inspector __

BELVILLE, NC, 28451