



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**14357-48-2022**  
State Number  
**21756**

EQUIPMENT INSPECTED

State Number: <b>21756</b>	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 3500	Manuf: OTIS	Speed: 125
Landings: 2	Installed: 08/18/2003	Rope Size: 0
Volts: 208	Complied: 08/22/2003	Entrances: 1

OWNER

HIGHEST PRAISE WORSHIP CTR  
19 RED BUG ROAD  
SHALLOTTE, NC, 28470

OCCUPANT

HIGHEST PRAISE WORSHIP CTR  
19 RED BUG ROAD  
SHALLOTTE, NC, 28470

INSPECTION INFORMATION

Inspection Date 12/23/2014	Type Inspection Not Inspected	Certificate Status Not Issued	Inspector 48 - Martin	County BRUNSWICK
-------------------------------	----------------------------------	----------------------------------	--------------------------	---------------------

10

VIOLATIONS

N/A

NO ACCESS

Elevator Name: # 1

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: UNAVAILABLE

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

HIGHEST PRAISE WORSHIP CTR  
19 RED BUG ROAD  
SHALLOTTE, NC, 28470