

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 15026-36-3511 State Number 24227

1

	F	EQUIPMENT INSPECTED			
State Number: 24227	Type of Unit: P	assenger	Floor to Floor: 1	to 3	
Capacity: 2000	Manuf: OTIS		Speed: 125		
Landings: 3	Installed: 10/31/2006		Rope Size: 0		
Volts: 208	Complied: 10/31/2006		Entrances: 1		
OWNER		OCCUPANT			
ELON UNIVERSITY	OAKS BUILDING (E)				
803 HAGGARD AVENUE	1004 ELON OAK TRAIL				
ELON, NC, 27744		ELON, NC, 27744			
	IN:	SPECTION INFORMATION			
Inspection Date 01/26/2015	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
NONE FOUND					
Elevator Name: BUILDING	(E)				
lotify the Elevator Bureau in write omplainace with current codes.	ting on Corrected Violations Form	when the following corrections l	have been made in order to bri	ng your equipment into	
iolations pointed out to: Bob 33					
	To make changes to the invoice mailing address please call: 919-733-0372				
THIS IS NOT AN INVOICE	An invoice will be mailed to:	ELON UNIVERSITY 803 HAGGARD AVENU ELON, NC, 27744	UE .		