



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
15028-16-4548
State Number
6858

EQUIPMENT INSPECTED

State Number: 6858	Type of Unit: Passenger	Floor to Floor: B to 2
Capacity: 2000	Manuf: WESTBROOK	Speed: 100
Landings: 3	Installed: 06/15/1972	Rope Size: 0
Volts: 220	Complied: 10/25/1993	Entrances: 1
OWNER	OCCUPANT	
BEAUFORT CO COURTHOUSE	BEAUFORT CO COURT HOUSE	
123 W THIRD ST	112 W SECOND ST	
WASHINGTON, NC, 27889	WASHINGTON, NC, 27889	

INSPECTION INFORMATION

Inspection Date 01/28/2015	Type Inspection Routine	Certificate Status Re-issued	Inspector 16 - Moore	County BEAUFORT
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

7

VIOLATIONS

8.6.4.7.1 Clean the elevator pit. Remove soiled oil pads from pit

Items must be corrected by: 02/27/2015

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Annette / Facility Maintenance

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

BEAUFORT CO COURTHOUSE
123 W THIRD ST
WASHINGTON, NC, 27889