



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
15034-54-1830
State Number
4865

EQUIPMENT INSPECTED

State Number: 4865	Type of Unit: Freight	Floor to Floor: 1 to 2
Capacity: 10000	Manuf: OTIS	Speed: 60
Landings: 2	Installed: 04/16/1963	Rope Size:
Volts: 560	Complied: 04/19/1990	Entrances: 2
OWNER	OCCUPANT	
AVOCA INC	AVOCA INC.	
PO BOX 129	841 AVOCA FARM ROAD	
MERRY HILL, NC, 27957	MERRY HILL, NC, 27957	

INSPECTION INFORMATION

Inspection Date 02/03/2015	Type Inspection Routine	Certificate Status Re-issued	Inspector 54 - Green	County BERTIE
-------------------------------	----------------------------	---------------------------------	-------------------------	------------------

8

VIOLATIONS

n/a No violations found

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: TOM RAY 252 482 2133

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

AVOCA INC
PO BOX 129
MERRY HILL, NC, 27957