

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927

Report Number 15049-36-1423 State Number 6259

1

	I	EQUIPMENT INSPECTED			
State Number: 6259	Type of Unit: Passe	nger	Floor to Floor: 1 to 3		
Capacity: 10000	Manuf: THYSSEN KRUPP		Speed: 60		
Landings: 2	Installed: 02/20/1969		Rope Size:		
Volts: 440	Complied: 02/20/1969		Entrances: 2		
OWNER		OCCUPANT			
AMI		AMI			
2609 TUCKER ST		204 N GRA-HOPEDALE RD			
BURLINGTON, NC, 27215		BURLINGTON, NC, 27215			
	IN:	SPECTION INFORMATION			
Inspection Date 02/18/2015	Type Inspection Removed	Certificate Status Not Issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
complainace with current codes. Violations pointed out to: N/A	iting on Corrected Violations Form	-	Inspector	ng your equipment into	
	To make changes to the invoice ma				
THIS IS NOT AN	AMI				
INVOICE	An invoice will be mailed to:	2609 TUCKER ST			

BURLINGTON, NC, 27215