



INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
15050-36-233
State Number
17863

EQUIPMENT INSPECTED

State Number: 17863	Type of Unit: Passenger	Floor to Floor: B to 2
Capacity: 4500	Manuf: THYSSEN KRUPP	Speed: 110
Landings: 4	Installed: 10/01/1998	Rope Size:
Volts: 200	Complied: 10/01/1998	Entrances: 2
OWNER	OCCUPANT	
DAVIS ST METHODIST CHURCH	DAVIS ST METHODIST CHURCH	
606 E DAVIS ST	606 E DAVIS ST	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 02/19/2015	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

1

VIOLATIONS

none found

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Alan sasser 336-226-4457

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

DAVIS ST METHODIST CHURCH
606 E DAVIS ST
BURLINGTON, NC, 27215