

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 15051-52-4741 State Number H1334

2

	EQ	UIPMENT INSPECTED			
State Number: H1334 Type of Unit: Ha		and Lift	Floor to Floor: 1 to 2		
Capacity: 750	Manuf: GARAVENTA		Speed: 11		
Landings: 2	Installed: 01/24/2003		Rope Size: 0		
Volts: 220	Complied: 01/24	1/2003	Entrances: 2		
OWNER		OCCUPANT			
ANTIOCH BAPTIST CHURCH	Ŧ	ANTIOCH BAP	ANTIOCH BAPTIST CHURCH		
580 ANTIOCH CHURCH ROAD		580 ANTIOCH CHURCH ROAD			
TAYLORSVILLE, NC, 28681		TAYLORSVILLE, NC, 28681			
	INSP	ECTION INFORMATION			
Inspection Date 02/20/2015	Type Inspection Routine	Certificate Status Re-issued	Inspector 52 - Sosebee	County ALEXANDER	
·		VIOLATIONS			
complainace with current codes.	ing on Corrected Violations Form wh	en the following corrections			
Violations pointed out to: Alma 8	28-632-2929 				
	To make changes to the invoice mailing address please call: 919-733-0372				
THIS IS NOT AN INVOICE	An invoice will be mailed to:	ANTIOCH BAPTIST C 580 ANTIOCH CHURC TAYLORSVILLE, NC,	CH ROAD		