



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
15061-16-0575
State Number
6917

EQUIPMENT INSPECTED

State Number: 6917	Type of Unit: Dumbwaiter	Floor to Floor: 1 to 2
Capacity: 300	Manuf: MATOT	Speed: 50
Landings: 2	Installed: 01/28/1971	Rope Size: 1/4
Volts: 270	Complied: 01/28/1971	Entrances: 1
OWNER	OCCUPANT	
BEAUFORT COUNTY COMM COLLEGE	BEAUFORT CO COMMUNITY COLLEGE	
5337 US HWY 264 EAST	5337 HWY 264 EAST	
WASHINGTON, NC, 27889	WASHINGTON, NC, 27889	

INSPECTION INFORMATION

Inspection Date 03/02/2015	Type Inspection Routine	Certificate Status Re-issued	Inspector 16 - Moore	County BEAUFORT
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

7

VIOLATIONS

n/a No violations found

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Melvin Lodge / Maintenance Chief

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

BEAUFORT COUNTY COMM COLLEGE
5337 US HWY 264 EAST
WASHINGTON, NC, 27889