N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
15063-4-1115
State Number
H1097

EQUIPMENT INSPECTED

State Number: **H1097**
Capacity: 750
Landings: 2
Volts: 120

Type of Unit: Hand Lift
Manuf: ACCESS
Installed: 03/29/2001
Complied: 04/04/2001

Floor to Floor: 1 to 2
Speed: 15
Rope Size: 0
Entrances: 2

OWNER
NEWLAND FIRST BAPTIST CHURCH
PO BOX 485
NEWLAND, NC, 28657

OCCUPANT
NEWLAND FIRST BAPTIST CHURCH
160 CRANBERRY STREET
NEWLAND, NC, 28657

INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County
03/04/2015	Routine	Re-issued	4 - Henegar	AVERY

6

VIOLATIONS

2.11.11.5.2 Provide the proper clearance (Min 3/4 between the hoistway wall and related panels, sills, and frames.

Items must be corrected by: 04/03/2015

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: Dr Jones 828-733-9092 Inspector _____

THIS IS NOT AN INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:
NEWLAND FIRST BAPTIST CHURCH
PO BOX 485
NEWLAND, NC, 28657