



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
15063-4-1119
State Number
9018

EQUIPMENT INSPECTED

| | | |
|---------------------------|-------------------------|------------------------|
| State Number: 9018 | Type of Unit: Passenger | Floor to Floor: 1 to 3 |
| Capacity: 2100 | Manuf: THYSSEN KRUPP | Speed: 125 |
| Landings: 3 | Installed: 11/02/1978 | Rope Size: 0 |
| Volts: 220 | Complied: 11/17/1978 | Entrances: 1 |

OWNER

AVERY COUNTY SCHOOLS
775 CRANBERRY STREET
NEWLAND, NC, 28657

OCCUPANT

AVERY COUNT MIDDLE SCHOOL
102 OLD MONTEZUMA ROAD
NEWLAND, NC, 28657

INSPECTION INFORMATION

| | | | | |
|-------------------------------|----------------------------|----------------------------------|--------------------------|-----------------|
| Inspection Date 03/04/2015 | Type Inspection Removed | Certificate Status Not Issued | Inspector 4 - Henegar | County AVERY |
|-------------------------------|----------------------------|----------------------------------|--------------------------|-----------------|

6

VIOLATIONS

- 8.11.1.6 Provide a metal periodic test date, the requirement number requiring the test, and the name of the person or firm performing the test inside the machine room
- 8.6.4.7.1 Clean the elevator pit.
- 2.13.5.1 Put the car door reopening devices in proper working order.

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Avery County 828-733-6006

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

AVERY COUNTY SCHOOLS
775 CRANBERRY STREET
NEWLAND, NC, 28657