NCDOL NCDOL M. Department of labor

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 15070-48-2724 State Number 23907

		EQUIPMENT INSPECTED			
State Number: 23907	Type of Unit: Pa	Type of Unit: Passenger		Floor to Floor: 1 to 4	
Capacity: 3000	Manuf: THYSSE	Manuf: THYSSEN KRUPP		Speed: 125	
Landings: 4	Installed: 06/15/2	Installed: 06/15/2006		Rope Size: .	
Volts: 208	Complied: 02/08	Complied: 02/08/2007		Entrances: 1	
OWNER		OCCUPANT			
CAM		ISLANDER RESORT - BLDG. #42			
P.O. BOX 8126		156 VIA OLD SOUND BLVD			
OCEAN ISLE BEACH, NC, 2	8469	OCEAN ISLE BEACH, NC, 28469			
	AI	ISPECTION INFORMATION			
Inspection Date 03/11/2015	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK	10
		VIOLATIONS			
2.27.1.1.2 Put the in car emer	e service feature in proper working of gency telephone in proper working of shall be provided. Damaged or mi	order.		IVE IN CAR]	

To make changes to the invoice mailing address please call: 919-733-0372

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into

THIS IS NOT AN INVOICE

complainace with current codes.

Items must be corrected by: 04/10/2015

Violations pointed out to: UNAVAILABLE

An invoice will be mailed to: P.O. BOX 8126

OCEAN ISLE BEACH, NC, 28469

Inspector ___