



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
15072-4-1068
State Number
24096

EQUIPMENT INSPECTED

State Number: 24096	Type of Unit: Passenger	Floor to Floor: 1F to 1R
Capacity: 2500	Manuf: SCHINDLER	Speed: 125
Landings: 2	Installed: 06/19/2006	Rope Size: 0
Volts: 208	Complied: 06/19/2006	Entrances: 2
OWNER	OCCUPANT	
GRANDFATHER COUNTRY CLUB	GRANDFATHER COUNTRY CLUB	
2120 HWY.105 NORTH	1225 HWY.105 NORTH	
LINVILLE, NC, 28646	LINVILLE, NC, 28646	

INSPECTION INFORMATION

Inspection Date 03/13/2015	Type Inspection Routine	Certificate Status Re-issued	Inspector 4 - Henegar	County AVERY
-------------------------------	----------------------------	---------------------------------	--------------------------	-----------------

6

VIOLATIONS

- 8.11.1.6 Provide a metal with test date, the requirement number requiring the test, and the name of the person or firm performing the test inside the machine room for all Categories 3,5 tests for electric elevators and 1, 3, 5 tests for hydraulic elevators
- 8.11.1.6 Provide the date of rupture valve test tag,

Items must be corrected by: 04/12/2015

Elevator Name: # 2

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Grandfather Country Club 828-896-4531

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

GRANDFATHER COUNTRY CLUB
2120 HWY.105 NORTH
LINVILLE, NC, 28646