



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
15077-36-0163
State Number
21190

EQUIPMENT INSPECTED

State Number: 21190	Type of Unit: Passenger	Floor to Floor: 1 to 3
Capacity: 2100	Manuf: SCHINDLER	Speed: 100
Landings: 3	Installed: 09/26/2002	Rope Size: 0
Volts: 480	Complied: 09/26/2002	Entrances: 1

OWNER

BELLMONT UNITED METHODIST
4039 MARKWOOD DRIVE
BURLINGTON, NC, 27215

OCCUPANT

BELLMONT UNITED METHODIST
4039 MARKWOOD DRIVE
BURLINGTON, NC, 27215

INSPECTION INFORMATION

Inspection Date 03/18/2015	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

1

VIOLATIONS

none found

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Jerry Jacson 336-227-463

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

BELLMONT UNITED METHODIST
4039 MARKWOOD DRIVE
BURLINGTON, NC, 27215