



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
15083-36-0643
State Number
23204

EQUIPMENT INSPECTED

State Number: 23204	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2500	Manuf: OTIS	Speed: 100
Landings: 2	Installed: 10/18/2005	Rope Size:
Volts: 480	Complied: 10/18/2005	Entrances: 1
OWNER	OCCUPANT	
CITY OF MEBANE	MEBANE PUBLIC LIBRARY	
106 EAST WASHINGTON ST	2ND & WASHINGTON ST	
MEBANE, NC, 27302	MEBANE, NC, 27302	

INSPECTION INFORMATION

Inspection Date 03/24/2015	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

1

VIOLATIONS

none found

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Sherry (919) 563-6431

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

CITY OF MEBANE
106 EAST WASHINGTON ST
MEBANE, NC, 27302