



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
15103-36-2745
State Number
2916

EQUIPMENT INSPECTED

State Number: 2916	Type of Unit: Dumbwaiter	Floor to Floor: B to 3
Capacity: 500	Manuf: MATOT	Speed: 50
Landings: 3	Installed: 04/15/1957	Rope Size: 3/8
Volts: 220	Complied: 03/20/2001	Entrances: 1
OWNER	OCCUPANT	
CAROLINA BIO SUPPLY	CAROLINA BIO SUPPLY	
2700 YORK RD	2700 YORK RD	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 04/13/2015	Type Inspection Removed	Certificate Status Not Issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	----------------------------------	---------------------------	--------------------

1

VIOLATIONS

This unit has been removed from service

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Glenn Walker 336-584-0387

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

CAROLINA BIO SUPPLY
2700 YORK RD
BURLINGTON, NC, 27215